

**From:** [Tighe, C. Daniel](#)  
**To:** [Moore, Gary](#)  
**Subject:** Adler poly containment  
**Date:** Thursday, March 26, 2015 8:47:01 AM  
**Attachments:** [removed.txt](#)

---

Gary,

As we discussed, the Adler poly containment and plastic runners were placed into service on 10.22.14 and were being cleaned on 11.12.14.

From looking at the pictures and notes in the logbook, the poly containment was damaged in that time period, somewhere around 11.7.14 when VB640 was removed from containment.

Please let me know if you need additional information.

Thanks,

Daniel



**C. Daniel Tighe, PMP**  
**Weston Solutions, Inc.**  
5599 San Felipe, Suite 700  
Houston, TX 77056  
713.985.6763 Direct  
713.397.1550 Cell  
713.985.6703 Fax

[Daniel.Tighe@WestonSolutions.com](mailto:Daniel.Tighe@WestonSolutions.com)

**CONFIDENTIALITY:** This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.

\*\*\*\*\* ATTACHMENT REMOVED \*\*\*\*\*  
\*\*\*\*\*

This message contained an attachment which the administrator has caused to be removed.

\*\*\*\*\* ATTACHMENT REMOVED \*\*\*\*\*  
\*\*\*\*\*

Attachment name: [image001.jpg]  
Attachment type: [image/jpeg]